



Setup:

- Setup Snow Cone machine on a secure table top
- Plug in power cord into electricity outlet.

Making Snow Cone:

- Fill the hopper to within an inch of the top with ice cubes.
- Switch the motor on. Wait for the motor to come to full speed (a minute or so).
- Push the pusher handle down against the ice in the hopper. Apply firm and even pressure to make the best snow. This allows the ice to resettle against the shaver head.
- Once ice has been shaved and has collected in the bottom compartment, use scoop to fill cone(s) with the shaved ice. Apply any flavored syrups as desired.
- Caution:** Never put any object into the snow cone machine body while the motor is running.

Serious damage can occur to any body parts or objects that are placed inside the snow cone machine hopper.

Potential Problems:

- Too much pressure will result in snow that is coarse; too little pressure will make the snow mushy.
- Make sure electricity cord is plugged into the electricity outlet or machine will not operate